Table 1. Summary of Results

Table 1. Summary of Results	SAMPLING LOCATION DESCRIPTION		INITIA	L SAMPLING	RESULTS	RE-SAI	MPLING RESU	LTS	CORRECTIVE ACTIONS POST		OST REMEDIATION SAMPLING RESULTS	
					Recommen	ded Level = 20ppb				Recon	nmended Level = 20ppb	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	
SAMPLING DATE			9/15/2018			mm/dd/yyyy		10/22/2018			mm/dd/yyyy	
RESULTS DATE			10/10/2018			mm/dd/yyyy		10/26/2018			mm/dd/yyyy	
DRINKING	NSGB-2124-A13-HALL-WFC-FD (BLDG 2124-5)	Fountain between A13 and A14	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
DRINKING	GTMO-2124-CWING-WFC-FD (BLDG 2124-16)	C-Wing courtyard between electric closet and janitor closet	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
DRINKING	GTMO-2124-DWING-WFC-FD (BLDG 2124-28)	D-Wing cooler fountain between restrooms	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
DRINKING	GTMO-2124-FWING-WFC-FD (BLDG 2124-37)	Cooler fountain in courtyard positioned to the left of ice machine	2.5	No	N/A	N/A	N/A	N/A		N/A	N/A	
DRINKING	GTMO-2124-FWING-BY GIRLS LOCKERROOM-WFC-FD (BLDG 2124-40)	Water fountain in F-Wing courtyard on girls locker room side	24	Yes	10/12/2018		71	1.9	Fixture removed 12/10/18.	N/A	N/A	
DRINKING	NSGB-2124-RM-RMES1-WFC-A-FD (BLDG 2124-44)	Cooler Fountain on Left , Elementary Trailers	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
DRINKING	NSGB-2124-RM-RMES1-WFC-B-FD (BLDG 2124-45)	Cooler Fountain on Right , Elementary Trailers	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
DRINKING	NSGB-2124-RM-RMES2-WFC-A-FD (BLDG 224-48)	Cooler Fountain on Left	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
DRINKING	NSGB-2124-RM-RMES2-WFC-B-FD (BLDG 2124-49)	Cooler Fountain on Right	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
DRINKING	NSGB-2124-RM-RMES3-WFC-A-FD (BLDG 2124-52)	Cooler Fountain on Left	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	

	SAMPLING LOCATION DESCRIPTION		INITIA	L SAMPLING			MPLING RESU	.TS	CORRECTIVE ACTIONS		POST REMEDIATION SAMPLING RESULTS Recommended Level = 20ppb	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture	Water Fountain	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds afte First Draw Sampling (ppb)	
SAMPLING DATE			9/15/2018					10/22/2018			mm/dd/yyyy	
RESULTS DATE			10/10/2018				10/26/2018	10/26/2018			mm/dd/yyyy	
DRINKING	NSGB-2124-RM-RMES3-WFC-B-FD (BLDG 2124-53)	Cooler Fountain on Right	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
DRINKING	NSGB-2124-RM-RMES4-WFC-A-FD (BLDG 2124-56)	Cooler Fountain on Left	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
DRINKING	NSGB-2124-RM-RMES4-WFC-B-FD (BLDG 2124-57)	Cooler Fountain on Right	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
DRINKING	NSGB-2124-RM-RMES5-WFC-A-FD (BLDG 2124-60)	Cooler Fountain on Left	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
DRINKING	NSGB-2124-RM-RMES5-WFC-B-FD (BLDG 2124-61)	Cooler Fountain on Right	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
DRINKING	NSGB-2124-RM-RMES6-WFC-A-FD (BLDG 2124-64)	Cooler Fountain on Left	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
DRINKING	NSGB-2124-RM-RMES6-WFC-B-FD (BLDG 2124-65)	Cooler Fountain on Right	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
DRINKING	NSGB-2124-RM-RMES7-WFC-A-FD (BLDG 2124-68)	Cooler Fountain on Left	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
DRINKING	NSGB-2124-RM-RMES7-WFC-B-FD (BLDG 2124-69)	Cooler Fountain on Right	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	

	SAMPLING LOCATION DESCRIPTION		INITIAI	L SAMPLING			MPLING RESU	LTS	CORRECTIVE ACTIONS		DIATION SAMPLING RESULTS
						ded Level = 20ppb				Recommended Level = 20ppb	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			9/15/2018			mm/dd/yyyy	10/22/2019	10/22/2018			mm/dd/yyyy
RESULTS DATE			10/10/2018			mm/dd/yyyy		10/26/2018			mm/dd/yyyy
DRINKING	NSGB-2124-RM-RMES8-WFC-A-FD (BLDG 2124-72)	Cooler Fountain on Left	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	NSGB-2124-RM-RMES8-WFC-B-FD (BLDG 2124-73)	Cooler Fountain on Right	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	NSGB-2124-K-K-FD (BLDG 2124-42)	Mobile kitchen by Elementary Trailers	1.2	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-2124-A12-BATH-GIRLS-HHWA-FD (BLDG 2124-1)	A-Wing - Girls restroom in A- Wing	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-2124-A12-BATH-GIRLS-HHWB-FD (BLDG 2124-2)		0.78	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-2124-A11-BATH-BOYS-HHWA-FD (BLDG 2124-3)	Ü	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-2124-A11-BATH-BOYS-HHWB-FD (BLDG 2124-4)		Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-2124-B18-BATH-BOYS-HHW-FD (BLDG 2124-6)	B-Wing - Administrative Building	0.73	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-2124-B19-BATH-GIRLS-HHW-FD (BLDG 2124-7)	B-Wing - Administrative Building	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-2124-B17-LOUNGE-HHW-FD (BLDG 2124-8)	B-Wing - Administrative Building	2.6	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-2124-B3-RM-HHW-FD (BLDG 2124-9)	B-Wing - Administrative Building	5.4	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-2124-B21-RM-HHW-FD (BLDG 2124-10)	B-Wing - Room between rooms B20 and B23	11	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-2124-C4-BATH-BOYS-HHWA-FD (BLDG 2124-11)	C-Wing - Boys restroom in C- Wing	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-2124-C4-BATH-BOYS-HHWB-FD (BLDG 2124-12)	C-Wing - Boys restroom in C- Wing	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-2124-C1-BATH-GIRLS-HHWA-FD (BLDG 2124-13)		2.7	No	N/A	N/A	N/A	N/A		N/A	N/A

	SAMPLING LOCATION DESCRIPTION		INITIAI	SAMPLING I			MPLING RESU	LTS	CORRECTIVE ACTIONS		POST REMEDIATION SAMPLING RESULTS	
						ded Level = 20ppb	1			Recommended Level = 20ppb		
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)		Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	
SAMPLING DATE			9/15/2018			mm/dd/yyyy	10/22/2018	10/22/2018			mm/dd/yyyy	
RESULTS DATE			10/10/2018			mm/dd/yyyy	10/26/2018				mm/dd/yyyy	
WASHING	GTMO-2124-C1-BATH-GIRLS-HHWB-FD (BLDG 2124-14)	C-Wing - Girls restroom in C- Wing	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	GTMO-2124-C5A-NURSE-HHW-FD (BLDG 2124-15)		2.0	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	GTMO-2124-C10-RM-STATION 1-HHWB- FD (BLDG 2124-17)	C-Wing Chemistry Classroom - Standard faucet	300	Yes	10/12/2018	N/A	15	0.4	Fixture removed 12/10/18.	N/A	N/A	
WASHING	GTMO-2124-C10-RM-STATION 2-HHWA- FD (BLDG 2124-18)		18	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	GTMO-2124-C10-RM-STATION 3-HHWA- FD (BLDG 2124-19)		7.0	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	GTMO-2124-C10-RM-STATION 3-HHWB- FD (BLDG 2124-20)		6.4	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	GTMO-2124-C10-RM-STATION 4-HHWA- FD (BLDG 2124-21)		82	Yes	10/12/2018	N/A	8.7	14	Fixture removed 12/10/18.	N/A	N/A	
WASHING	GTMO-2124-C10-RM-STATION 4-HHWB- FD (BLDG 2124-22)		160	Yes	10/12/2018	N/A	7.9	3.1	Fixture removed 12/10/18.	N/A	N/A	
WASHING	GTMO-2124-C10-RM-STATION 5-HHWB- FD (BLDG 2124-23)		76	Yes	10/12/2018	N/A	33	0.75	Fixture removed 12/10/18.	N/A	N/A	
WASHING	GTMO-2124-C10-RM-STATION 6-HHWA- FD (BLDG 2124-24)		8.6	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	NSGB-2124-C10-HOOD-HHW-FD (BLDG 2124-25)		240	Yes	10/12/2018	N/A	63	4.9	Fixture removed 12/10/18.	N/A	N/A	
WASHING	GTMO-2124-C12-RM-HHW-FD (BLDG 2124-26)	C-Wing - Science Classroom	7.8	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	GTMO-2124-D2-BATH-GIRLS-HHW-FD (BLDG 2124-27)	D-Wing - Girls restroom in D- Wing	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	GTMO-2124-D1-BATH-BOYS-HHW-FD (BLDG 2124-29)	D-Wing - Boys restroom in D- Wing	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	GTMO-2124-D10-RM-HHWA-FD (BLDG 2124-30)	D-Wing - Art Classroom	4.0	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	GTMO-2124-D10-RMHHWB-FD (BLDG 2124-31)	D-Wing - Art Classroom	1.3	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	GTMO-2124-D10-RMHHWC-FD (BLDG 2124-32)	D-Wing - Art Classroom (Sink in back of classroom)	8.1	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	GTMO-2124-E10-BATH-BOYS-HHWA-FD (BLDG 2124-33)		1.1	No	N/A	N/A	N/A	N/A		N/A	N/A	

	SAMPLING LOCATION DESCRIPTION		INITIA	L SAMPLING			MPLING RESU	LTS	CORRECTIVE ACTIONS		DIATION SAMPLING RESULTS
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Recomment Date Fixture Secured? (See Note 1)	ded Level = 20ppb Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	mended Level = 20ppb Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			9/15/2018			mm/dd/yyyy	10/22/2018	10/22/2018			mm/dd/yyyy
RESULTS DATE			10/10/2018			mm/dd/yyyy	10/26/2018	10/26/2018			mm/dd/yyyy
WASHING	GTMO-2124-E10-BATH-BOYS-HHWB-FD (BLDG 2124-34)	E-Wing - Boys restroom in gym	0.88	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-2124-E10-BATH-GIRLS-HHWA-FD (BLDG 2124-35)	E-Wing - Girls restroom in gym	10	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-2124-E10-BATH-GIRLS-HHWB-FD (BLDG 2124-36)	E-Wing - Girls restroom in gym	8.4	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-2124-F14-BATH-BOYS-HHW-FD (BLDG 2124-38)	F-Wing - Sink in boys locker room	5.0	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	GTMO-2124-F7-BATH-GIRLS-HHW-FD (BLDG 2124-39)	Sink in girls locker room - F- Wing	13	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	NSGB-2124-K-HHW-FD (BLDG 2124-41)	Hand wash sink in kitchen, Mobile Kitchen by Elementary Trailers	0.75	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	NSGB-2124-RM-RMES1-LHW-FD (BLDG 2124-43)	Low Hand Wash , Elementary School Trailers	1.5	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	NSGB-2124-UBATH-RMES1-LHW-FD (BLDG 2124-46)	Low Hand Wash in Bathroom , Elementary School Trailers	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	NSGB-2124-RM-RMES2-LHW-FD (BLDG 2124-47)	Low Hand Wash , Elementary School Trailers	1.1	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	NSGB-2124-UBATH-RMES2-LHW-FD (BLDG 2124-50)	Low Hand Wash in Bathroom , Elementary School Trailers	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	NSGB-2124-RM-RMES3-LHW-FD (BLDG 2124-51)	Low Hand Wash , Elementary School Trailers	4.2	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	NSGB-2124-UBATH-RMES3-LHW-FD (BLDG 2124-54)	Low Hand Wash in Bathroom , Elementary School Trailers	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	NSGB-2124-RM-RMES4-LHW-FD (BLDG 2124-55)	Low Hand Wash , Elementary School Trailers	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	NSGB-2124-UBATH-RMES4-LHW-FD (BLDG 2124-58)	Low Hand Wash in Bathroom , Elementary School Trailers	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	NSGB-2124-RM-RMES5-LHW-FD (BLDG 2124-59)	Low Hand Wash , Elementary School Trailers	2.4	No	N/A	N/A	N/A	N/A		N/A	N/A

	SAMPLING LOCATION DESCRIPTION		INITIAL	SAMPLING	RESULTS	RE-SAI	MPLING RESU	LTS	CORRECTIVE ACTIONS	POST REME	DIATION SAMPLING RESULTS	
					Recommen	ded Level = 20ppb				Recon	Recommended Level = 20ppb	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds aftr First Draw Sampling (ppb)	
SAMPLING DATE			9/15/2018			mm/dd/yyyy	10/22/2018	10/22/2018			mm/dd/yyyy	
RESULTS DATE			10/10/2018			mm/dd/yyyy	10/26/2018	10/26/2018			mm/dd/yyyy	
WASHING	NSGB-2124-UBATH-RMES5-LHW-FD (BLDG 2124-62)	Low Hand Wash in Bathroom , Elementary School Trailers	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	NSGB-2124-RM-RMES6-LHW-FD (BLDG 2124-63)	Low Hand Wash , Elementary School Trailers	4.3	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	NSGR-2124-LIBATH-RMFS6-LHW-FD	Low Hand Wash in Bathroom , Elementary School Trailers	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	NSGB-2124-RM-RMES7-LHW-FD (BLDG 2124-67)	Low Hand Wash , Elementary School Trailers	1.3	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	NSGB-2124-LIBATH-RMFS7-LHW-FD	Low Hand Wash in Bathroom , Elementary School Trailers	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	NSGB-2124-RM-RMES8-LHW-FD (BLDG 2124-71)	Low Hand Wash , Elementary School Trailers	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	I NISGR-2124-LIBATH-RMESS-LHW/-FD	Low Hand Wash in Bathroom , Elementary School Trailers	4.2	No	N/A	N/A	N/A	N/A		N/A	N/A	

¹ Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 20ppb.

² Post-remediation sampling was initially conducted on (DATE). Additional (ACTIONS) were implemented and final results below recommended level of 20 ppb for samples collected on (DATE) are shown on the table.

	SAMPLING LOCATION DESCRIPTION			SAMPLING I			MPLING RESU	LTS	CORRECTIVE ACTIONS	CORRECTIVE ACTIONS POST REMEDIATION SAMPLE	
				Recommen	ded Level = 20ppb			Recommended Level = 20ppb			
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	,	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE RESULTS DATE			9/15/2018 10/10/2018			mm/dd/yyyy mm/dd/yyyy	10/22/2018 10/26/2018				mm/dd/yyyy mm/dd/yyyy

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS		RE-SAMPLING RESULTS		POST REMEDIATION RESULTS		
		•	Recom	mended Level = 20ppb			
	First Draw (ppb)	Water Fountain	First Draw (ppb)	Follow up Flush	First Draw (ppb)		
		Follow up Flush Sample - Collected day before First		- Collected 30 seconds after First Draw Sampling			
		Draw Sampling		(ppb)			
		(ppb)		(ррь)			
		WF-7					
Total Drinking	21	0	1	1	0		
Total Drinking > 20 ppb	1	0	1	0	0		
Total Cook/Brush	1	0	0	0	0		
Total Cook/Brush > 20 ppb	0	0	0	0	0		
Total Washing	52	0	5	5	0		
Total Washing > 20 ppb	5	0	2	0	0		
Total Samples	74	0	6	6	0		
Total Samples > 20 ppb	6	0	3	0	0		